



U.S. Department
of Transportation
**Federal Aviation
Administration**

Memorandum

This page represents the document as presented. The following page represents the document without any obscurities.

Subject: INFORMATION
Accident; AAL

September 11, 2001

From: Boston ATCT

To: Aircraft Accident

This transcription covers the Boston ATCT Local Control West position for the time period from September 11, 2001, 1151 UTC to September 11, 2001, 1202 UTC.

Agencies Making Transmissions

Abbreviations

Boston ATCT, Local Control West
American Airlines 11

LCW
AAL

I hereby certify that the following is a true transcription of the recorded conversations pertaining to the subject aircraft accident involving AAL11:

Allan R. Turmelle
Certified Professional Controller
Boston ATCT


1151
1152
1153
1154
1155
1156

1156:27 LCW

amer
bravo

1156:34 AAL

taxi to runway via bravo then nineteen one american eleven heavy





U.S. Department
of Transportation
**Federal Aviation
Administration**

Memorandum

Subject: **INFORMATION:** Partial Transcript; Aircraft
Accident; AAL11; September 11, 2001 UTC

Date: September 11, 2001

From: Boston ATCT

Reply to
Attn. of:

To: Aircraft Accident File

This transcription covers the Boston ATCT Local Control West position for the time period from September 11, 2001, 1151 UTC to September 11, 2001, 1202 UTC.

Agencies Making Transmissions

Abbreviations

Boston ATCT, Local Control West
American Airlines 11

LCW
AAL

I hereby certify that the following is a true transcription of the recorded conversations pertaining to the subject aircraft accident involving AAL11:

Allan R. Turmelle
Certified Professional Controller
Boston ATCT

1151
1152
1153
1154
1155
1156

1156:27 LCW american eleven heavy boston tower taxi to runway four right via bravo and monitor the tower one one niner point one

1156:34 AAL taxi to four right uh via bravo then nineteen one american eleven heavy

AAL11

Page 2 of 2

1157

1158

1159

1200

1201

1202

End of Transcript